

AD-A072 254

BAKER (MICHAEL) JR INC BEAVER PA
NATIONAL DAM INSPECTION PROGRAM. MEADVILLE DAM (NDI NUMBER PA-0--ETC(U)
MAY 79 C Y CHEN

F/G 13/2


DACW31-79-C-0011

NL

UNCLASSIFIED

1 OF 1
AD
A072. 54





MICROCOPY RESOLUTION TEST CHART
NATIONAL BUREAU OF STANDARDS-1963-A

Distribution Unlimited
Approved for Public Release
Contract No. DACW31-79-C-0011✓



OHIO RIVER BASIN

MEADVILLE DAM
CRAWFORD COUNTY, COMMONWEALTH OF PENNSYLVANIA
NDI No. PA 00177
PennDER No. 20-48
SCS No. PA 460

PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM

⑥ National Dam Inspection Program. Mead-
ville Dam (NDI Number PA-00177, P
PennDER Number 20-48, SCS Number PA-460),
Ohio River Basin, Mill Run, Crawford
County, Pennsylvania. Phase I Inspection Report,

Prepared for: DEPARTMENT OF THE ARMY
Baltimore District, Corps of Engineers
Baltimore, Maryland 21203

Prepared by: MICHAEL BAKER, JR., INC.
Consulting Engineers
4301 Dutch Ridge Road
Beaver, Pennsylvania 15009

⑫ 96p.

Date: ⑪ May 22 1979

⑮ DACW 31-79-C-0011

⑩ Chuan Yuan Chen

503

410 795

79 08 06 060

PREFACE

This report was prepared under guidance contained in the "Recommended Guidelines for Safety Inspection of Dams," for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I Investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through frequent inspections can unsafe conditions be detected and only through continued care and maintenance can these conditions be prevented or corrected.

Phase I Inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established guidelines, the spillway design flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. The spillway design flood provides a measure of relative spillway capacity and serves as an aid in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

| | | | |
|--------------------|---------------|--------------|---------|
| ACCESSION FOR | NTIS GCM&I | Dist | A |
| | DLIC TAB | Avail and/or | special |
| | Unannounced | | |
| | Justification | | |
| By | | | |
| Distribution/ | | | |
| Availability Codes | | | |

**PHASE I REPORT
NATIONAL DAM INSPECTION PROGRAM**

Meadville Dam, Crawford County, Pennsylvania
NDI No. PA 00177, PennDER No. 20-48, SCS No. PA 460
Mill Run
Inspected 1 December 1978

**ASSESSMENT OF
GENERAL CONDITIONS**

Meadville Dam is a zoned earthfill dam designed by the Soil Conservation Service (SCS), U.S. Department of Agriculture. The dam has a crest length of 420 feet, a height of 40 feet, and a storage capacity of 30 acre-feet at normal pool. Meadville Dam is classified as a "High" hazard-"Intermediate" size dam.

Visual inspection and review of engineering data in December 1978 and April 1979 indicate no serious deficiencies requiring emergency attention. The dam was found to be in good overall condition at the time of inspection; however, several minor items of remedial work should be performed in the near future. These items include:

- 1) Repair the manually operated control for the pond drain.
- 2) The eroded areas should be regraded, treated and seeded with an appropriate mixture to prevent erosion.
- 3) The catch basin drain in the auxiliary spillway should be cleared of debris.


The owner should continue in the future to inspect the embankment and concrete appurtenances, and repair as necessary. In addition, the following operational measures are recommended to be undertaken by the owner:

- 1) Develop a detailed emergency operation and warning system.
- 2) During periods of unusually heavy rain, provide around-the-clock surveillance of the dam.
- 3) When warning of a storm of major proportions is given by the National Weather Service, the owner should activate the emergency operation and warning system.

Hydraulic/hydrologic evaluations, performed in accordance with procedures established by the Baltimore District, Corps of Engineers, for Phase I Inspection Reports, revealed that the spillway will pass the Probable Maximum Flood (PMF) without overtopping the dam. The spillway is therefore considered "adequate."

Submitted by:

MICHAEL BAKER, JR., INC.



C. Y. Chen
C. Y. Chen, Ph.D., P.E.
Engineering Manager-Geotechnical

Date: 25 May 1979


Approved by:

DEPARTMENT OF THE ARMY
BALTIMORE DISTRICT, CORPS OF ENGINEERS


G. K. Withers
G. K. WITHERS
Colonel, Corps of Engineers
District Engineer

Date: 14 Jun 79

MEADVILLE DAM



**Overall View of Downstream Embankment and Concrete Spillway
(Note Erosion Channel on Embankment)**



**Overall View of Upstream Face of Dam from Dike on East Abutment
(Note Ruts and Erosion on Face of Dam)**

TABLE OF CONTENTS

| | <u>Page</u> |
|---|-------------|
| Section 1 - Project Information | 1 |
| Section 2 - Engineering Data | 5 |
| Section 3 - Visual Inspection | 6 |
| Section 4 - Operational Procedures | 8 |
| Section 5 - Hydraulic/Hydrologic | 9 |
| Section 6 - Structural Stability | 11 |
| Section 7 - Assessment, Recommendations/Remedial Measures | 12 |

PLATES

| | |
|----------|--|
| Plate 1 | - Location Plan |
| Plate 2 | - Watershed Map |
| Plate 3 | - Plan of Storage Areas |
| Plate 4 | - Plan of Dam Site |
| Plate 5 | - Plan of Dam Site |
| Plate 6 | - Plan - Profile of Principal Spillway |
| Plate 7 | - Riser Details |
| Plate 8 | - Reinforced Concrete Stilling Basin Details |
| Plate 9 | - Emergency Spillway Cross-Sections |
| Plate 10 | - Emergency Spillway Cross-Sections |
| Plate 11 | - Seepage Drain Details - Embankment |

APPENDICES

| | |
|------------|---|
| Appendix A | - Check List - Visual Inspection and Field Sketches |
| Appendix B | - Check List - Engineering Data |
| Appendix C | - Photographs |
| Appendix D | - Hydrologic and Hydraulic Computations |
| Appendix E | - Regional Geology |

PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM
MEADVILLE DAM

NDI No. PA 00177, PennDER No. 20-48, SCS No. PA 460

SECTION 1 - PROJECT INFORMATION

1.1 GENERAL

- a. Authority - The Dam Inspection Act, Public Law 92-367, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a program of inspection of dams throughout the United States.
- b. Purpose of Inspection - The purpose of the inspection is to determine if the dam constitutes a hazard to human life or property.

1.2 DESCRIPTION OF PROJECT

- a. Description of Dam and Appurtenances - Meadville Dam, locally known as Rainbow Lake, is a zoned earthfill dam with a crest height of 40 feet and an embankment length of 420 feet. The upstream face has a slope of 3H:1V (Horizontal to Vertical) with a 10-foot wide berm at El. 1164.0 feet. This berm provides access to the riser unit. The downstream face has a slope of 2H:1V. The crest of the embankment is 15 feet wide. A cutoff trench is provided in the embankment, with a minimum depth of 3 feet and a bottom width of 12 feet.

→ The protective dike around adjacent Meadville High School is also a zoned earthfill embankment. The upstream face near the auxiliary spillway has a slope of 3H:1V and the downstream face has a slope of 2H:1V. After a transition section at original Station 12+00, both the upstream and downstream slopes are 5H:1V. The dike has an approximate crest length of 1335 feet (excluding the auxiliary spillway).

← The outlet works (principal spillway) consist of a pond drain, concrete riser unit, conduit and stilling basin. An 18-inch bituminous coated corrugated metal pipe is used as the pond drain and has an inlet at the upstream toe. Flow from the pond drain into the riser is controlled by a sluice gate which is hand-operated from the top of the riser. The crest of the riser is at El. 1163.5 feet. The conduit to the stilling basin is a 42-inch reinforced concrete water pipe placed on a concrete cradle.

A reinforced concrete weir box and concrete chute spillway is constructed in the right abutment area. The crest elevation of the overflow spillway is 1184.3 feet. The overflow spillway is 260 feet long. The channel has a width of 50 feet and a length from the upper end to the control section of 260 feet. The control section is an ogee overflow weir, 7.25 feet above the floor of the channel. The floor of the channel is 15 inches thick; the retaining walls are as high as 30 feet and are reinforced with 92 counterfort sections.

- b. Location - Meadville Dam is located on Mill Run approximately 1.25 miles upstream of its confluence with French Creek and 150 feet east of Morgan Street in the city of Meadville.
- c. Size Classification - The dam is 40 feet high and has a maximum storage capacity of 850 acre-feet. Therefore, the dam is in the "Intermediate" size category.
- d. Hazard Classification - Due to the proximity of the city of Meadville, Pennsylvania, many lives could be lost in the event of failure of the dam. Therefore, this dam is considered in the "High" hazard category.
- e. Ownership - The dam is owned by the city of Meadville, 984 Water Street, Meadville, Pennsylvania 16335.
- f. Purpose of Dam - The dam was designed as a flood control structure. However, the reservoir and surrounding area are also used for recreation.
- g. Design and Construction History - Meadville Dam was designed in 1962 by the U.S. Soil Conservation Service (SCS). The dam was constructed in 1963 and 1964 by Smith Construction Company.
- h. Normal Operational Procedures - The dam has no formal operating procedures. Normal pool is maintained by the riser crest at El. 1163.5 feet. An 18-inch bituminous coated corrugated metal pipe connected to the pond drain, with invert El. 1157.5 feet, can be opened during periods of heavy rain to minimize flooding of recreational facilities around the dam.

1.3 PERTINENT DATA

- a. Drainage Area (square miles) - 7.96

b. Discharge at Dam Site (c.f.s.) -

| | |
|--|---------|
| Maximum Flow - | Unknown |
| Ungated Spillway Capacity at Maximum Pool Elevation (El. 1189.5 ft.) - | 10,100 |

c. Elevation [feet above Mean Sea Level (M.S.L.) -

| | |
|----------------------------------|--------|
| Minimum Top of Dam - | 1189.5 |
| Design Top of Dam - | 1189.8 |
| Maximum Pool - | 1189.5 |
| Normal Pool - | 1163.5 |
| Streambed at Centerline of Dam - | 1150 |

d. Reservoir (miles) -

| | |
|--------------------------|-----|
| Length of Maximum Pool - | 0.8 |
| Length of Normal Pool - | 0.2 |

e. Storage (acre-feet) -

| | |
|------------------------------------|-----|
| At Normal Pool (El. 1163.5 ft.) - | 30 |
| At Maximum Pool (El. 1184.3 ft.) - | 471 |
| At Top of Dam (El. 1189.5 ft.) - | 850 |

f. Reservoir Surface (acres) -

| | |
|--------------------------------|-------|
| Top of Dam (El. 1189.5 ft.) - | 74.0+ |
| Normal Pool (El. 1163.5 ft.) - | 4.0 |

g. Dam -

| | |
|---------------------------------------|-----------------|
| Type - | Zoned earthfill |
| Length (feet) - | 420 |
| Height (feet) - | 40 |
| Top Width (feet) - | 15 |
| Slopes - Upstream - | 3H:1V |
| (with 10-foot berm at El. 1164.0 ft.) | |
| Downstream - | 2H:1V |

Zoning - The embankment is constructed of three zones -- the core section consists of impervious fill made up of clays and silty clays, the downstream zone is mixed sand and gravel, and the upstream zone contains more pervious material composed of sands and gravels.

Impervious Core - Clay and silty clay

Cutoff - The cutoff trench is in the embankment foundation. The trench was excavated to a minimum depth of 3 feet and has a 12-foot bottom width. The bottom of the cutoff trench rests on impermeable glacial till.

Grout Curtain -
Dike -

None
Zoned embankment

h. Diversion and Regulating Tunnel (Principal Spillway) -

Type - Drop Inlet with 42 inch reinforced concrete water pipe placed on a concrete cradle. Five anti-seepage collars are provided along the pipe at intervals of 24 feet.

Length of Conduit (feet) - 175.33
Access - Through top of concrete riser
Weir Elevation (feet M.S.L.) - 1163.5
Weir Size (feet) (four inlets) - 4 by 3.5

i. Spillway (Auxiliary Spillway) -

Type - Reinforced concrete weir box
and chute channel spillway
Width of Channel (feet) - 50
Crest Elevation (feet M.S.L.) - 1184.3
Gates - None
Upstream Channel (Length in feet) - 288
(from upper end to the control section)

Downstream Channel - Final 28-foot section is level at El. 1159.3 feet. The control section is an ogee overflow weir, 7.25 feet above the floor of the channel. The channel discharges into a 50-foot-wide grass-lined channel.

j. Regulating Outlets - Manually operated 18-inch sluice gate located at bottom of riser.

SECTION 2 - ENGINEERING DATA

2.1 DESIGN

Available design data which were considered necessary for a Phase I Investigation of Meadville Dam were furnished by the Pennsylvania Department of Environmental Resources (PennDER) from File No. 20-48. The file included:

- 1) Operation and maintenance reports from the SCS.
- 2) Several letters of correspondence between the SCS and the city of Meadville.
- 3) Photographs taken during the construction of Meadville Dam.
- 4) Permits for construction.
- 5) Hydrologic/hydraulic calculations for the dam performed by SCS personnel.
- 6) Quantity calculations of the dam and appurtenances computed by SCS personnel.
- 7) A complete set of design drawings for the dam and appurtenances.

2.2 CONSTRUCTION

The dam was constructed by the Smith Construction Company in 1963 and 1964. No progress reports concerning the status of construction were available in PennDER's files. However, some correspondence including photographs and in-place density test results were included.

2.3 OPERATION

The city of Meadville, owner of the dam, is responsible for all operation and maintenance.

2.4 EVALUATION

- a. Availability - PennDER File No. 20-48 contained a full set of design drawings for the Meadville Dam.
- b. Adequacy - The information available is generally adequate for a Phase I Inspection.
- c. Validity - There is no reason at the present time to believe that the available engineering data is inaccurate or misleading.

SECTION 3 - VISUAL INSPECTION

3.1 FINDINGS

a. General - The inspection was made on 1 December 1978. No unusual weather conditions were experienced and the lake was at normal pool. The dam and appurtenant structures were found, in general, to be in good overall condition at the time of inspection. The problems noted during the visual inspection are considered minor and do not require immediate remedial treatment. Noteworthy deficiencies observed are described briefly in the following paragraphs. The complete visual inspection check list and field sketches are given in Appendix A.

b. Dam - Along the dike south of the auxiliary spillway, vehicular traffic has caused rutting along the east slope and crest. Pedestrian traffic has worn a pathway in the grass cover from Meadville High School east of the dike, over the dike, up the south slope of the dam, and along the crest of the dam (see field sketches for location). Erosion was also observed along the chain link fence around the auxiliary spillway. A drainage path has eroded down the slope behind the wing wall on the right side of the auxiliary spillway. A small path has also developed on the left side of the auxiliary spillway and right abutment of the dam.

On the downstream face of the embankment, a major channel has eroded approximately 100 feet from the left abutment. The channel is 2 feet wide by 1 foot deep and extends from the crest to the toe of the embankment. Two minor channels, 6 inches by 6 inches, have also eroded approximately 50 feet on either side of the larger one and typically begin 2 to 3 feet below the crest. The downstream face is covered with thick, tall vegetation.

c. Appurtenant Structures - Several erosion areas were observed around the outlet structure. The areas between the head wall and chain-link fence on both the right and left side are eroded, as is the area just outside the fence on the right side. An eroded area also was noted at the end of the wing wall on the left side. Small animal holes are located on the right side of the end of the wing wall. The concrete head wall and sandstone wing walls are in good condition.

The sluice gate control for the pond drain was not operating properly at the time of the inspection. According to information from the local personnel, the gate was last opened in the Spring of 1977 and in order to operate the gate a bolt had to be removed from down inside the riser structure. The 6-inch diameter embankment drain outlets were not visible due to the amount of water flowing from the 42-inch outlet pipe and therefore no assessment could be made of their operation. The catch basin drain in the auxiliary spillway is covered with debris.

The concrete walls along the auxiliary spillway are in good condition with the exception of some minor spalling along the outside of the south end wall. Some cracks were also noted on the walls adjacent to the spillway. The differential movement of the walls and wing walls was noted. According to the local representatives of the city of Meadville, the SCS (designer of the dam) is studying the problem. The movement was first noted in the SCS annual inspection report dated 17 May 1968.

- d. Reservoir Area - No problems were observed in the reservoir area. Reservoir slopes are gently sloping to moderately steep with a good cover of grasses or stands of forests.

Approximately two miles upstream from Meadville Dam on Mill Run is Tamarack Lake Dam "A" (NDI No. PA 00177).

- e. Downstream Channel - The outlet channels for the principal spillway and auxiliary spillway showed no signs of past erosion. The channel banks are gently sloping with established vegetation. The dam is located within the city of Meadville and the downstream channel (Mill Run) flows through a major portion of both the residential and business community of Meadville. It cannot be estimated how many homes or businesses might be affected by a dam failure, but more than likely it would be greater than 100. A 13 May 1956 flood which occurred prior to construction of the dam caused an appraised (1956 value) damage of \$170,000. This flood was of a magnitude that is likely to occur on the average once every 40 years.

SECTION 4 - OPERATIONAL PROCEDURES

4.1 PROCEDURES

No formal operational procedures are used for Meadville Dam since it is a flood control structure and does not require the use of water supply intake valves or gates. The reservoir under normal operating conditions remains at approximate El. 1163.5 feet and has 20.8 feet of additional storage to the crest of the emergency spillway.

4.2 MAINTENANCE OF DAM

The city of Meadville has an annual inspection program for the dam assisted by the SCS. Maintenance which is normally performed on a biweekly schedule by personnel of the Department of Public Works, Parks Division, includes removal of debris, repairing eroded areas, revegetating bare spots and mowing grass.

4.3 MAINTENANCE OF OPERATING FACILITIES

The city of Meadville, Department of Public Works, Parks Division, personnel are responsible for maintenance of the riser. The park superintendent visits the dam during heavy rainfall to check the trash rack and check for flow over the auxiliary spillway.

4.4 DESCRIPTION OF ANY WARNING SYSTEM IN EFFECT

At the present time, there is no warning system or evacuation plan in the event of a dam failure.

4.5 EVALUATION OF OPERATIONAL ADEQUACY

Maintenance of the operating facilities are considered adequate for the functions that they serve; however, formal records of lift gate inspections should be instituted. In addition, formal emergency procedures should be developed as recommended in paragraph 7.2.

SECTION 5 - HYDRAULIC/HYDROLOGIC

5.1 EVALUATION OF FEATURES

- a. Design Data - Hydrologic and hydraulic calculations were obtained from the PennDER files. According to SCS design criteria by which Meadville Dam was designed, the emergency spillway and freeboard hydrographs were developed and routed through the reservoir to establish the elevations of the design high water and crest of dam. These hydrographs were developed by combining discharges from the north spillway of Tamarack Lake (dam site "A"), located approximately 1.7 miles upstream, as well as uncontrolled runoff from the tributary drainage area below Tamarack Lake. The results of the rainfall and hydrograph calculations used in the analysis are summarized as follows:

RAINFALL AND HYDROGRAPH CALCULATIONS

| <u>Hydrograph</u> | <u>Six-Hour Rainfall (inches)</u> | | <u>Resulting</u> |
|-----------------------|-----------------------------------|----------------------------|---|
| | <u>Tamarack Lake</u> | <u>Meadville Reservoir</u> | <u>Hydrograph</u> <u>Peak</u> <u>(c.f.s.)</u> |
| Emergency Spillway | 8.8 | 9.1 | 6969 |
| Freeboard | 17.7 | 18.3 | 13043 |

The resulting elevations of the design high water and crest of dam are 1187.3 feet and 1189.8 feet, respectively.

- b. Experience Data - Extensive flooding from Mill Run occurred in the city of Meadville prior to construction of the Meadville Dam. The maximum reservoir stage since construction of the dam was approximately 4 feet above normal pool. No other reservoir experience records were available for the preparation of this report.
- c. Visual Observations - At the time of the inspection, no condition was observed that would indicate that the spillway and outlet works could not operate satisfactorily in the event of a flood.

- d. Overtopping Potential - Meadville Dam is classified as a "High" hazard-"Intermediate" size dam requiring evaluation for a spillway design flood (SDF) equal to the Probable Maximum Flood (PMF). The outlet works and spillway consist of a concrete drop-inlet and a concrete weir box which exits into a concrete chute. The hydrologic and hydraulic capabilities of the reservoir, outlet works, and spillway were evaluated by routing the PMF through the reservoir with the aid of the U.S. Army Corps of Engineer's Flood Hydrograph Package, HEC-1. Runoff from the uncontrolled drainage basin tributary to Meadville Dam as well as outflows from Tamarack Lake (Dam "A"), were considered in the hydrologic analysis. The resulting PMF hydrograph, therefore, had a peak discharge of 5943 c.f.s. based on a 6-hour rainfall of 21.9 inches. The results of the flood routing indicate that the reservoir is capable of passing the PMF with a corresponding reservoir level of El. 1187.9 feet. This maximum reservoir stage is 1.6 feet below the actual dam crest at El. 1189.5 feet.
- e. Spillway Adequacy - The dam, as outlined in the above analysis, is capable of passing the PMF without overtopping. Therefore, the spillway is classified as "adequate" according to the recommended criteria.

SECTION 6 - STRUCTURAL STABILITY

6.1 EVALUATION OF STRUCTURAL STABILITY

- a. Visual Observations - No structural inadequacies were noted during the visual inspection of Meadville Dam.
- b. Design and Construction Data - No construction records were available; however, the stability calculations contained in the design records were reviewed during the preparation of this report. The review indicates that there should be no cause for concern for the structural stability of the earth embankment or appurtenances. The embankment as designed should be sufficiently stable due to the fill height and moderate slopes of the dam. The toe or foundation drains were designed to intercept seepage through the permeable material and to control the phreatic line in the embankment. The minor differential movement of the auxiliary spillway walls was not considered severe enough to create a stability problem.
- c. Operating Records - The last yearly inspection (dated 22 July 1977) conducted by the SCS and local representatives indicated the wing walls and retaining walls appear to have stabilized and no new movement could be detected.
- d. Post-Construction Changes - No alterations of the dam were apparent since it was constructed.
- e. Seismic Stability - Meadville Dam is in Seismic Zone 1 of the "Seismic Zone Map of the Contiguous United States," Figure 1, page D-30, "Recommended Guidelines for Safety Inspection of Dams." This is a zone of very low seismic activity. As indicated in paragraph 6.1.b., Meadville Dam could be shown to meet the static stability requirements of the "Recommended Guidelines for Safety Inspection of Dams." As a result, no further consideration of seismic stability is considered necessary under the present circumstances.

SECTION 7 - ASSESSMENT, RECOMMENDATIONS/REMEDIAL MEASURES

7.1 DAM ASSESSMENT

- a. Safety - Meadville Dam is designed to prevent overtopping under conditions equal to PMF. No seepage was observed during the visual inspection when the reservoir was at normal pool. The dam was found to be in good overall condition.
- b. Adequacy of Information - The information available and the observations made during the field inspection are considered sufficient for this Phase I Inspection Report.
- c. Urgency - The owner should initiate the action discussed in paragraph 7.2 without delay.
- d. Necessity for Additional Data/Evaluation - Since the Meadville Dam meets the requirements of the hydrologic evaluation guidelines as set forth in "Recommended Guidelines for Safety Inspection of Dams" and does not appear to have any deficiencies in its structural stability, the need for any additional investigation is not warranted.

7.2 RECOMMENDATIONS/REMEDIAL MEASURES

The inspection and review of information revealed certain items of work which should be performed in a timely manner by the owner. These include:

- 1) The manually operated controls for the pond drain should be repaired and maintained to ensure their proper operation.
- 2) The eroded areas should be regraded, fertilized and seeded with an appropriate mixture to prevent erosion.
- 3) The catch basin drain in the auxiliary spillway should be cleared of debris, and in the future, this task should be part of a routine maintenance schedule.
- 4) The location of the dam between Meadville High School and a residential area of the city of Meadville presents special problems. The heavy pedestrian traffic causes damage to the grass cover both on the dam crest and

embankment slopes. It is recommended that the owner investigate the possibility of installing a proper walkway along this route by placing gravel across the crest of the dam and a stairway on the upstream and downstream face.

- 5) All motor vehicles such as trail bikes and all-terrain vehicles should be strictly prohibited from the embankment. The motor vehicle traffic on the dike embankment should also be restricted.

The owner should continue in the future to inspect the embankment and concrete appurtenances, and repair as necessary.

In addition, the following operational measures are recommended to be undertaken by the owner:

- 1) Develop a detailed emergency operation and warning system.
- 2) During periods of unusually heavy rain, provide around-the-clock surveillance of the dam.
- 3) When warning of a storm of major proportions is given by the National Weather Service, the owner should activate the emergency operation and warning system.

PLATES


















PLATE I LOCATION PLAN
MEADVILLE DAM







GEOLOGIC INVESTIGATION DATE: AUG. 61
UNIFIED CLASSIFICATION SYMBOLS AND DESCRIPTIONS BY VISUAL INSPECTION.



TYPICAL SECTIONS OF DAM




TP-117

DH-118

TP-120

REPORT NO. *7-111*
 DATE *May 62*

RECEIVED IN THE OFFICE OF THE WATER & SOIL CONSERVATION DIVISION
 U.S. DEPARTMENT OF AGRICULTURE
 WASHINGTON, D.C.



- CONVERT ALL FILL AS CLASS B-2 95% STD PROCTOR
- SECTION 1 CL. ML. MATERIAL AS REPRESENTED BY THE LOG OF TP 115 FROM 0.5' TO 12.0' AND DH-118 FROM 0.5' TO 10.0' TO BE USED ALSO IN CUTOFF TRENCH AND AROUND NORMAL SPILLWAY.
 - SECTION 2 THE MORE HEAVY DUS. GW-3M MATERIAL REPRESENTED BY THE LOG OF TP-111 FROM 2.0' TO 10.0'.
 - SECTION 3 GW-3M MATERIAL AS REPRESENTED BY THE LOG OF TP 114 FROM 0.5' TO 12.0'.

THIS PAGE IS BEST QUALITY REPRODUCTION FROM COPY FURNISHED TO DDC

NOTE:
 NO EXCAVATION ABOVE CONTOUR 1180.5 IN SOIL AREA A (CITY DATUM 1710) OR BELOW ELEV 1180.5

PLATE 3 *2*




Note: Approx. Half Scale

MILL RUN WATERSHED PROJECT
 CRAWFORD COUNTY, PENNSYLVANIA
 FLOODWATER RETARDING DAM NO. 460
PLAN OF STORAGE AREAS
U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

| | |
|------------------------------|----------------|
| Prepared by FD THEURER | Date May 62 |
| Checked by W.D. CARPENTER | Date May 62 |
| Drawn by J.W. DICK | Date May 62 |

PA-460-P

TYPICAL SECTIONS OF DAM



ELEV. 11600
THINLY BEDDED
SANDY SHALES OF THE
BEDDING OF FINE,
GR., SORT

CONTOUR MAP
OF THE HORNED LAGOON
SHORELINE INVESTIGATION
WAS, 1970, SHOWS
AT 5.5

FILE # 1159-6

7
10
12
14
16
18
20


THRU
LAWD, MILTY NAME, ON
DOIT, MONT
ONE DO TACKLE AND
WING TO CLOAK IN
SOUTH PLANT W/ TWO
MOT, BOUNTY FOR DO

JANOR HLT GR, OR
TRACE OF INDICATE,
MONT ARAD

[illegible]

ELEV = 1155 @
 TYPICAL BLACK
 DUSTY GRASS, 10 TO 15,
 100%
 AND GRASSES, 100% LENSES,
 10 TO 15, 100% DEEP
 AND, 100% GRASS, 100%
 SLIGHTLY SANDY, 100% HARD,
 10 TO 15, 100% GRASS, 100%
 OF GRASS, 100% GRASS TO HATTEN


NOT TO SCALE



| | |
|-----------|-------------|
| REF PT #1 | S 43° 20' W |
| REF PT #2 | N 17° 19' W |
| REF PT #3 | S 45° 47' E |

BUILDING
 CONTOUR
 2043
 RAD LINE
 EASTING SCALE
 EASTING SCALE TO BE REMOVED

TEST OF IN DEEL - HOLE
CLEARING LIMIT
CLEARING AND GAUGING LIMIT



FOR FENCE DETAILS SEE SHEET 23

TP-108

ELEV. 1172.9
 10' TOPSOIL, SILT
 20' SILT SAND & GRAVEL
 30' SILT SAND & GRAVEL
 40' SILT SAND & GRAVEL
 50' SILT SAND & GRAVEL
 60' SILT SAND & GRAVEL
 70' SILT SAND & GRAVEL
 80' SILT SAND & GRAVEL
 90' SILT SAND & GRAVEL
 100' SILT SAND & GRAVEL

TP-109

ELEV. 1171.3
 10' TOPSOIL
 20' SILT SAND & GRAVEL
 30' SILT SAND & GRAVEL
 40' SILT SAND & GRAVEL
 50' SILT SAND & GRAVEL
 60' SILT SAND & GRAVEL
 70' SILT SAND & GRAVEL
 80' SILT SAND & GRAVEL
 90' SILT SAND & GRAVEL
 100' SILT SAND & GRAVEL

TP-110

ELEV. 1170.8
 10' TOPSOIL
 20' SILT SAND & GRAVEL
 30' SILT SAND & GRAVEL
 40' SILT SAND & GRAVEL
 50' SILT SAND & GRAVEL
 60' SILT SAND & GRAVEL
 70' SILT SAND & GRAVEL
 80' SILT SAND & GRAVEL
 90' SILT SAND & GRAVEL
 100' SILT SAND & GRAVEL

DH-207

ELEV. 1180.6
 10' TOPSOIL
 20' SILT SAND & GRAVEL
 30' SILT SAND & GRAVEL
 40' SILT SAND & GRAVEL
 50' SILT SAND & GRAVEL
 60' SILT SAND & GRAVEL
 70' SILT SAND & GRAVEL
 80' SILT SAND & GRAVEL
 90' SILT SAND & GRAVEL
 100' SILT SAND & GRAVEL

RECEIVED IN THE OFFICE OF THE WATER & FOREWATERS ON THE DAY OF 1962

FILE NUMBER

REPORT NO. 77-11-11

FOR

SEE REPORT NO.

THIS PAGE IS BEST QUALITY PHOTOGRAPH FROM COPY FURNISHED TO DDC




PLATE 4 2

Scale: Approx. Half Scale

MILL RUN WATERSHED PROJECT
 CRAWFORD COUNTY, PENNSYLVANIA
 FLOODWATER RETARDING DAM PA 460

PLAN OF DAMSITE


U.S. DEPARTMENT OF AGRICULTURE
 SOIL CONSERVATION SERVICE

| | | |
|-----------------|---------|-------------|
| Designed by | Dr. | Approved by |
| FD THEUERER | May '62 | |
| Drawn | | |
| RL DREIBACH | Aug '61 | |
| Traced | | |
| GE VAN BUSHKIRK | May '62 | |
| Checked | | |

Sheet No. 3 of 3

PA-460-P

SEE FENCE DETAILS SEE SHEET 23




20-4854
FILE NUMBER
RECEIVED IN THE WATER & POWER
RESOURCES DIVISION
DEPARTMENT OF AGRICULTURE
WASHINGTON, D.C. 20250
JUL 15 1962
File Clerk

RECD FOR
SEE REPORT NO. 2256
Date

4.4.62
C.D. McConville
Chief Engineer

NORTH

THIS PAGE IS BEST QUALITY PHOTOGRAPH
FROM COPY FURNISHED TO DDC




2


PLATE 5

Note: Approx. Half Scale

| | |
|--|-------------------------|
| MILL RUN WATERSHED PROJECT CRAWFORD COUNTY, PENNSYLVANIA FLOODWATER RETARDING DAM PA-460 | |
| PLAN OF DAMSITE | |
| U.S. DEPARTMENT OF AGRICULTURE SOIL CONSERVATION SERVICE | |
| Designed by F. D. THEURER | Date MAY '62 |
| Drawn by T. H. REE | Date JULY '62 |
| Checked by R. A. STALTER | Date JULY '62 |
| Scale 4" = 100' | Project No. PA-460-P |



PLAN OF PRINCIPAL SPILLWAY




PROFILE OF PRINCIPAL SPILLWAY
NOT TO SCALE

| JOINT | DISTANCE FROM RISER | INVERT ELEV. OF 42\"/> |
|-------|---------------------|------------------------|
| J-1 | 0.33 | 1142.00 |
| J-2 | 16.33 | 1148.92 |
| J-3 | 32.33 | 1148.83 |
| J-4 | 48.33 | 1148.75 |
| J-5 | 64.33 | 1148.67 |
| J-6 | 80.33 | 1148.58 |
| J-7 | 96.33 | 1148.50 |
| J-8 | 112.33 | 1148.20 |
| J-9 | 128.33 | 1147.30 |
| J-10 | 144.33 | 1147.60 |
| J-11 | 160.33 | 1147.30 |
| J-12 | 176.33 | 1147.00 |
| I | 26.33 | 1148.86 |
| II | 50.33 | 1148.74 |
| III | 74.33 | 1148.61 |
| IV | 98.33 | 1148.46 |
| V | 120.33 | 1148.05 |


NOTE: PIPE LENGTHS
ARE BASED ON NOMINAL LENGTH
AND DO NOT INCLUDE CREEP.


MAX CAMBER: 0.5 FT @ JOINT J-6

TP-107



TP-122






PLAN OF PRINCIPAL SPILLWAY

20-48-1A
 RECEIVED IN THE OFFICE OF THE WATER & POWER
 RESOURCES BOARD, DEPARTMENT OF FORESTS &
 WATERS ON THE 11 DAY OF May, A.D. 1962
 File Clerk

1. TO LAST OUTSIDE JOINT AND
 WITH CONCRETE ON NE 1/2 SECTION


RECD. FOR
 SEE REPORT NO. *[Signature]*
 Div. Dam

42" DIA. REINF. CONC. WATER PIPE
 (1) 10' SECTIONS
 (1) WALL PIECE FOR 12" WALL
 TOTAL = 177.33'
 PRESSURE HEAD = 38 FT.
 LOAD = 36,300 LBS. PER LIN. FT. BASED ON 48" O.D.
 MIN. EDGE BEARING STRENGTH FOR GOOD CRACK (PRESTRESSED)
 EQUALS 3330 LBS. PER LIN. FT.
 MIN. EDGE BEARING STRENGTH FOR GOOD CRACK (NON-PRESTRESSED)
 EQUALS 2200 LBS. PER LIN. FT.



PROFILE OF PRINCIPAL SPILLWAY
 NOT TO SCALE

DAY LINE FOR SAILFALL 310' FROM S



TYPICAL SECTION OF PRINCIPAL SPILLWAY EXCAVATION

TP-122

LAND SURVEY, MAPS, PLANS, ETC. ARE
 BASED ON THE SURVEY OF THE
 15' TYPICAL SPILLWAY EXCAVATION
 IN CRAWFORD COUNTY, PENNSYLVANIA
 DET. DATED AT ABOUT 11'

1.5' TYPICAL SPILLWAY EXCAVATION
 4.0' TYPICAL SPILLWAY EXCAVATION

THIS PAGE IS BEST QUALITY REPRODUCTION
 FROM COPY FURNISHED TO DDC

Note: Approx. Half Scale **PLATE 6**

MILL RUN WATERSHED PROJECT
 CRAWFORD COUNTY, PENNSYLVANIA
 FLOODWATER RETARDING DAM PA 460

PLAN-PROFILE OF PRINCIPAL SPILLWAY
 U.S. DEPARTMENT OF AGRICULTURE
 SOIL CONSERVATION SERVICE

| | | |
|-------------------------------|-----------------|----------------------------|
| DESIGNED BY F. D. THEUERER | DATE May '62 | APPROVED BY [Signature] |
| DRAWN BY MINIROLICH | DATE May '62 | APPROVED BY [Signature] |
| SCALE 1" = 10' | DATE May '62 | APPROVED BY [Signature] |

PA-460-P

SYMMETRICAL
ABOUT C



THE CONCRETE CRADLE SHALL HAVE JOINT
AT EACH PIPE JOINT.
4" PREFORMED BIT TYPE JOINT - ALL
SPEC ASTM D-56-43 OR D-56-
WILL BE PLACED BETWEEN CRADLE JOINT



SLIDE GATE NOTES:

The diagram illustrates a three-stage cross-flow heat exchanger. It consists of three horizontal tubes labeled A, B, and C from top to bottom. Each tube has a vertical flow path indicated by dashed lines. The tubes are connected to a central vertical pipe. Inlet and outlet ports are labeled A, B, C, and D. The flow path is shown as a central vertical dashed line passing through the tubes.

Figure 1 is a plan view of a rectangular reinforced concrete slab. The slab is 12'0" wide and 12'0" deep. It features a central square column. The reinforcement layout is shown with top bars (circles with numbers) and bottom bars (circles with numbers). The "OUTSIDE FACE" is on the left and the "INSIDE FACE" is on the right. Dimensions for bar spacing and placement are provided.

Technical drawing of a rectangular box with dimensions and labels. The drawing shows the box from a top-down perspective. The outer dimensions are labeled as 10" (15) 12" for the width and 9" (15) 12" for the length. The inner dimensions are labeled as 8" (15) 10" for the width and 7" (15) 10" for the length. The drawing includes labels for the "OUTSIDE FACE - EACH WALL" and "INSIDE FACE - EACH WALL". The drawing also shows the box with a lid, with the lid dimensions labeled as 10" (15) 12" and 9" (15) 12". The drawing includes a small detail of a corner joint.

TRASH RACK DETAILS SHEET 19

12'-6"

3'-6"

6" RAD

3'-6"

F

E

SEAL WITH COMPOUND

12' | 12' 3'-6" 12' | 12'

7'-6"

3'-6"


6" O.D.

[illegible][illegible]


SECTION A-A

DETAILS OF REINFORCED CONCRETE RISER

THE CONCRETE CRADLE SHALL HAVE JOINTS AT EACH PIPE JOINT. JOINTS SHALL BE PERFORMED BY TYPE "X" WELD. SPEC. ASTM A-562-48 OR A-562-49. WELLS SHALL BE PLACED BETWEEN CRADLES.



SUGGESTED CONCRETE SUPPORT BLOCK



TYPICAL CONSTRUCTION JOINT



STEEL SCHEDULE

| BAR | LOCATION | SIZE | LENGTH | NO. | A | B | C | TOTAL |
|-----|----------|------|--------|------|---|-----|-----|-------|
| 1 | WIDER | 16 | 5 | 13-6 | 1 | | | 168 |
| 2 | | 2 | 5 | 12-6 | 1 | | | 25 |
| 3 | | 2 | 5 | 7-0 | 1 | | | 18 |
| 4 | | 12 | 6 | 4-7 | 2 | 1-8 | 1-1 | 183 |
| 5 | | 8 | 6 | 13-1 | 2 | 3-6 | 1-7 | 184 |
| 6 | | 6 | 6 | 11-2 | 2 | 1-7 | 1-7 | 187 |
| 8 | | 16 | 6 | 9-9 | 2 | 3-6 | 6-3 | 196 |
| 9 | | 16 | 6 | 9-9 | 2 | 3-6 | 6-1 | 214 |
| 10 | | 12 | 6 | 10-0 | 1 | | | 180 |
| 11 | | 6 | 6 | 9-3 | 1 | | | 111 |
| 12 | | 12 | 6 | 10-0 | 1 | | | 213 |
| 13 | | 12 | 6 | 4-6 | 1 | | | 54 |
| 14 | | 12 | 6 | 4-6 | 1 | | | 39 |
| 15 | | 16 | 6 | 8-0 | 1 | | | 384 |
| 16 | | 2 | 6 | 9-9 | 1 | | | 13 |
| 17 | | 9 | 6 | 4-0 | 1 | | | 96 |
| 18 | | 38 | 5 | 6-3 | 1 | | | 313 |
| 19 | | 12 | 5 | 11-4 | 1 | | | 258 |
| 20 | | 12 | 4 | 8-3 | 2 | 4-3 | 4-0 | 75 |
| 21 | | 24 | 4 | 12-0 | 1 | | | 288 |
| 22 | | 48 | 4 | 3-6 | 1 | | | 168 |
| 23 | | 9 | 4 | 3-0 | 1 | | | 18 |
| 24 | | 8 | 4 | 5-3 | 1 | | | 42 |

| C | COLLARS (S) | NO. | SIZE | LENGTH | NO. | A | B | C | TOTAL |
|----|-------------|-----|------|--------|-----|---|---|---|-------|
| C1 | | 6 | 4 | 1-9 | 1 | | | | 105 |
| C2 | | 4 | 4 | 9-3 | 1 | | | | 370 |
| C3 | | 3 | 4 | 13-6 | 1 | | | | 405 |
| C4 | | 5 | 4 | 3-9 | 1 | | | | 181 |
| C5 | | 2 | 4 | 6-0 | 1 | | | | 120 |

20-415-11
FILE NUMBER
RECEIVED IN THE OFFICE OF THE WATER & POWER RESOURCES DIVISION, U.S. DEPARTMENT OF AGRICULTURE, WASHINGTON, D.C. MAY 19 1962
FILED

RECD. FOR
SEE REPORT NO. 20-415-11
Div. Date



SAR TYPES
1
STEEL (THIS SHEET ONLY)
NO. 4 BARS 1770 LIN. FT. 1187 LBS.
NO. 5 BARS 700 LIN. FT. 1792 LBS.
NO. 6 BARS 181 LIN. FT. 1545 LBS.
TOTAL LBS. 4524



CONCRETE (THIS SHEET ONLY)
CLASS "B" 240 CU YDS (MINIMUM)
CLASS "D" 743 CU YDS (MINIMUM) (SEE NOTE 1)

- GENERAL NOTES:
- ALL CONCRETE SHALL BE OF THE CLASS INDICATED ON THE DRAWINGS.
 - PORTLAND CEMENT TYPE I WITH 36 A-1 ENTRAINING ADMIXTURE OR TYPE IN SHALL BE USED.
 - ALL REINFORCING STEEL TO BE LAPPED A MIN. OF 30 BAR DIAMETERS.
 - ALL REINFORCING STEEL PLACED IN CONCRETE POURED AGAINST THE GROUND SHALL HAVE A MINIMUM OF 3" CLEAR COVER. WHERE FORMS ARE USED SHALL HAVE A MINIMUM OF 2" CLEAR COVER.
 - ALL EXPOSED EDGES OF CONCRETE TO HAVE 90° CHAMFER UNLESS OTHERWISE NOTED.
 - ALL METAL PARTS NOT GALVANIZED TO BE PAINTED. SPEC. 12-58


PLATE 7
SCALE 1/4" = 1'-0"

MILL RUN WATERSHED PROJECT
CRAWFORD COUNTY, PENNSYLVANIA
FLOODWATER RETARDING DAM PA-460
RISER DETAILS
U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE


Approved: May 62
Checked: June 62
Designed: June 62
Drawn: June 62
PA-460-P



THIS PAGE IS BEST QUALITY PRACTITIONER COPY FURNISHED TO EDO




SECTION ON CENTERLINE




SECTION A-A


NOTE FIELD BEND REINFORCING BARS
TO AVOID 6" DOWN PIPES.




PLAN VIEW




SECTION C-C




SECTION ON CENTERLINE



SECTION A-4





| | |
|--|--|
| 7-11-62 | |
| FILE NO. | |
| RECEIVED IN THE OFFICE OF THE WATER & POWER RESOURCES DIVISION DEPARTMENT OF AGRICULTURE | |
| WATERS ON THE DAY OF MAY 1962 | |
| File Clerk | |

| | |
|----------------|-----|
| RECD | FOR |
| SEE REPORT NO. | |

7-11-62
J. H. Morgan
Ch. Eng.

Note: Approx. Half Scale

PLATE 9

MILL RUN WATERSHED PROJECT
CRAWFORD COUNTY, PENNSYLVANIA
FLOODWATER RETARDING DAM PA-460

EMER. SPWY. X-SECTIONS


U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

| | |
|---------------------------|------------------|
| Designed F. C. THEURER | Date May '62 |
| Drawn W. H. MORGAN | Date June '62 |
| Checked T. H. IFFT | Date AUG-62 |

Sheet No. 21 of 25

PA-460-P

THIS PAGE IS BEST QUALITY REPRODUCTION
FROM COPY FURNISHED TO DDC




| | |
|---------------------------|----------|
| RECEIVED IN | FILE NO. |
| DEPARTMENT OF AGRICULTURE | DATE |
| WATERS OF THE | DAY OF |
| | A.D. 19 |


| | |
|------------|------|
| REPORT NO. | DATE |
| 72511 | |



7+00



6+50



5+91



5+50

THIS PAGE IS BEST QUALITY PHOTOGRAPH
FROM COPY FURNISHED TO DDC


| | | | |
|--|-------------------|----------------------------|------------------|
| Note: Approx. No. 7 Scale | | PLATE 10 | |
| MILL RUN WATERSHED PROJECT CRAWFORD COUNTY, PENNSYLVANIA FLOODWATER RETARDING DAM #1-460 | | | |
| EMER. SPWY. X-SECTIONS | | | |
| U.S. DEPARTMENT OF AGRICULTURE SOIL CONSERVATION SERVICE | | | |
| Designed by F.D. THEURER | Date May 62 | Approved by W.H. MORGAN | Date 62 |
| Drawn by T.H. LIFT | Scale 1" = 20' | Sheet No. 22 | File PA-460-P |

2


FOR PROFILE ALONG EMERGENCY SPILLWAY DRAIN SEE SHEET 7
FOR PROFILE ALONG S.A.F. DRAIN SEE SHEET 8

EMANKMENT DRAIN 6" DIA. — B.C.
678 FT PERFORATED
40 FT NON-PERFORATED

END 7+70 ——— EMBANKMENT DRAIN
END 4+70 ——— EMERGENCY SPILLWAY DRAIN
——— S.A.F. DRAIN




INLET OF 6" DIA. OUTLET
PIPES ARE AT THE SAME
ELEVATION AS THE PRINCIPAL
SPILLWAY



PLAN VIEW SCALE 1" = 60'

| STATION | DISTANCE TO E. OF EM SPILLWAY |
|-------------|-------------------------------|
| END 0+70 | 16.67' |
| END 0+90 | 36.67' |
| END 3+30 | 40.00' |
| END 3+34 | 41.00' |
| END 3+53.25 | 43.50' |
| END 4+26 | 43.50' |





END 0+00 = 0+51 ON E. OF CHUTE
END 0+00 = 0+70 ON EMER SPILLWAY DRAIN




PROFILE ALONG CENTERLINE OF EMBANKMENT DRAIN

SCALE HORIZ 1" = 60' VERT

EMBAKMENT DRAIN 6" DIA - B.C.C.M.P.
678 FT PERFORATED
40 FT NON-PERFORATED



SECTION C-C SCALE 1" = 3'
BETWEEN STA. 6+26 AND 6+97
STA. 6+50 TO 6+54 IS THE
SAME EXCEPT PIPE IS OMITTED.



DISTANCE TO E. OF EM SPILLWAY
36.67'
36.67'
40.00'
41.00'
43.50'
43.50'




PLATE II

MILL RUN WATERSHED PROJECT
CRAWFORD COUNTY, PENNSYLVANIA
FLOODWATER RETARDING DAM PA-460

SEEPAGE DRAIN DETAILS - EMBANKMENT
U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

| | | |
|---------------------------|-----------------|------------------------|
| Designed J. M. Zuplo | Date JUNE 67 | Approved by Title |
| Drawn B. J. SEPANEK | Date JUNE 67 | Title |
| Checked F. A. THOMPSON | Date JUNE 67 | Sheet No. 5 of 5 |
| Drawing No. PA-460-P | | |

NOTE: Approx. Half Scale

THIS PAGE IS BEST QUALITY REPRODUCTION
FROM COPY FURNISHED TO DOD

2

APPENDIX A

CHECK LIST - VISUAL INSPECTION
AND FIELD SKETCHES

Check List
Visual Inspection
Phase 1

A-1

Name of Dam Meadville Dam County Crawford State PA Coordinates Lat. N 41° 38.3'
NDI # PA 00177
Pennder # 20-48 Long. W 80° 8.2'

Date of Inspection 1 Dec. 1978 Weather Cloudy Temperature 55°F.

Pool Elevation at Time of Inspection 1163.7 ft. M.S.L. Tailwater at Time of Inspection 1148.6 ft. M.S.L.

Inspection Personnel:

Michael Baker, Jr., Inc.:

James G. Ulinski
Rodney E. Holderbaum
David F. Johns

Owner's Representative
City of Meadville:

Kenneth A. Beers, Jr., Public Works
John Coulter
Joe Damico

David F. Johns Recorder

CONCRETE/MASONRY DAMS - Not Applicable

A-2

Name of Dam: HEADVILLE DAM
NDI # PA 00177

| VISUAL EXAMINATION OF | OBSERVATIONS | REMARKS OR RECOMMENDATIONS |
|-----------------------|--------------|----------------------------|
|-----------------------|--------------|----------------------------|

LEAKAGE

STRUCTURE TO
ABUTMENT/EMBANKMENT
JUNCTIONS

DRAINS

WATER PASSAGES

FOUNDATION

CONCRETE/MASONRY DAMS - Not Applicable

A-3

Name of Dam: MEADVILLE DAM
DOI # PA 00177

| VISUAL EXAMINATION OF | OBSERVATIONS | REMARKS OR RECOMMENDATIONS |
|-----------------------|--------------|----------------------------|
|-----------------------|--------------|----------------------------|

| | | |
|-------------------------------------|--|--|
| SURFACE CRACKS CONCRETE SURFACES | | |
|-------------------------------------|--|--|

| | | |
|---------------------|--|--|
| STRUCTURAL CRACKING | | |
|---------------------|--|--|

| | | |
|--------------------------------------|--|--|
| VERTICAL AND HORIZONTAL ALIGNMENT | | |
|--------------------------------------|--|--|

| | | |
|-----------------|--|--|
| MONOLITH JOINTS | | |
|-----------------|--|--|

| | | |
|---------------------|--|--|
| CONSTRUCTION JOINTS | | |
|---------------------|--|--|

EMBANKMENT

A-4

Name of Dam: MEADVILLE DAM
NDI # PA 00177

| VISUAL EXAMINATION OF | OBSERVATIONS | REMARKS OR RECOMMENDATIONS |
|-----------------------|--------------|----------------------------|
|-----------------------|--------------|----------------------------|

| | | |
|----------------|----------------------------------|--|
| SURFACE CRACKS | No surface cracks were observed. | |
|----------------|----------------------------------|--|

| | | |
|---|---|--|
| UNUSUAL MOVEMENT OR CRACKING AT OR BEYOND THE TOE | No bulges, cracks, or apparent earth movements were observed at or beyond the embankment toe. | |
|---|---|--|

SLOUGHING OR EROSION OF EMBANKMENT AND ABUTMENT SLOPES

1. On the east slope of the dike, south of the auxiliary spillway, vehicular traffic has caused rutting of the slope. Rutting has also occurred along the crest south of the auxiliary spillway.

1. The rutted areas should be regraded, treated, and seeded.

(cont. on p. A-5)

2. Pedestrian traffic has caused a large pathway to be worn through the grass cover from Meadville High School east of the dike, over the dike, up the south slope of the dam, and along the crest of the dam.

2. These areas should be regraded, treated, and seeded with an appropriate mixture to prevent erosion.

3. A rut was observed along the outside of the chain-link fence around the auxiliary spillway.

3. The area should be regraded, treated, and seeded as necessary.

4. A ditch, 0.5 ft. wide by 0.4 ft. deep and approximately 10 ft. long, has eroded down to the slope behind the wing wall on the right side of the auxiliary spillway. The left side also has an erosion ditch of equal proportion.

4. The ditch should be regraded, treated, and seeded. If the problem is recurring, a paved drainage ditch should be provided.

EMBANKMENT

A-5

Name of Dam: HEADVILLE DAM
 NOI # PA 00177

| VISUAL EXAMINATION OF | OBSERVATIONS | REMARKS OR RECOMMENDATIONS |
|--|---|---|
| SLOUGHING OR EROSION OF EMBANKMENT AND ABUTMENT SLOPES (Continued) | 5. On the downstream face of the embankment 100 ft. from the left abutment, a major erosion channel approximately 2 ft. wide and 1 ft. deep has developed. Smaller channels have eroded at 50 ft. and 150 ft. from the left abutment. | 5. These areas should be regraded, treated, and seeded. Effort should be made to prohibit motorcycles from traversing the slopes. |
| VERTICAL AND HORIZONTAL ALIGNMENT OF THE CREST | 1. Vertical Alignment--The surveyed crest shows a slight variation in elevation across the crest due to erosion caused by pedestrian and vehicular traffic. 2. Horizontal Alignment--No misalignment was observed. | 1. The crest should be regraded, treated, and seeded. |
| RIPRAP FAILURES | No riprap was placed on the upstream slope. Very slight erosion of the 2H:1V slope was observed on the embankment. | The limited areas of slope erosion should be regraded and seeded. Minor erosion should be repaired promptly. If serious erosion occurs in the future, riprap protection may become necessary. |
| JUNCTION OF EMBANKMENT AND ABUTMENT, SPILLWAY AND DAM | No problems were noted. | |

EMBANKMENT

A-6

Name of Dam: HEADVILLE DAM
 NDI # PA 00177

| VISUAL EXAMINATION OF | OBSERVATIONS | REMARKS OR RECOMMENDATIONS | |-----------------------|--------------|----------------------------| |-----------------------|--------------|----------------------------|

ANY NOTICEABLE SEEPAGE

None

STAFF GAGE AND RECORDER

None

DRAINS

1. The drain in the auxiliary spillway is covered with debris.
1. The drain should be cleaned as part of a routine preventative maintenance schedule.
2. The embankment drains could not be assessed due to the amount of water flowing in the outlet basin.

OUTLET WORKS

Name of Dam: HEADVILLE DAM
DOI # PA 00177

| <u>VISUAL EXAMINATION OF</u> | <u>OBSERVATIONS</u> | <u>REMARKS OR RECOMMENDATIONS</u> |
|--|--|---|
| CRACKING AND SPALLING OF CONCRETE SURFACES IN OUTLET CONDUIT | The wing walls and head walls are in good condition. | |
| INTAKE STRUCTURE | The concrete on the drop-inlet structure is in good condition. | |
| OUTLET STRUCTURE | No noticeable defects were observed except for the erosion between the head wall and chain-link fence. | Eroded areas should be treated and seeded with an appropriate mixture to prevent erosion. |
| OUTLET CHANNEL | A small area has eroded at the end of the left wing wall. | The area should be treated and seeded. If the problem recurs, riprap should be provided to prevent erosion. |
| EMERGENCY GATE | The sluice gate for operation of the 18-in. pond drain was not in proper working condition. | The gate should be repaired or replaced as necessary. |

Name of Dam: HEADVILLE DAM
NDI # PA 00177

UNGATED SPILLWAY (Auxiliary Spillway)

A-8

| <u>VISUAL EXAMINATION OF</u> | <u>OBSERVATIONS</u> | <u>REMARKS OR RECOMMENDATIONS</u> |
|------------------------------|---------------------|-----------------------------------|
|------------------------------|---------------------|-----------------------------------|

CONCRETE WEIR

None

APPROACH
CHANNEL

1. Some minor spalling was observed on the south wall of the channel. 1. The concrete should be repaired as necessary.
2. Some cracks were observed on the vertical walls adjacent to the dam abutment. 2. The cracks should be repaired as necessary.
3. Some movement of the walls along the channel was noted. 3. According to the local personnel, the SCS is making a study of this movement since it was noted in their 17 May 1968 annual inspection.

DISCHARGE CHANNEL

The downstream channel is an earth channel with grass lining and is in good condition.

BRIDGE AND PIERS

None

GATED SPILLWAY - Not Applicable

A-9

Name of Dam: MEADVILLE DAM
DOI # PA 00177

| VISUAL EXAMINATION OF | OBSERVATIONS | REMARKS OR RECOMMENDATIONS |
|-----------------------|--------------|----------------------------|
|-----------------------|--------------|----------------------------|

CONCRETE SILL

APPROACH CHANNEL

DISCHARGE CHANNEL

BRIDGE AND PIERS

GATES AND OPERATION
EQUIPMENT

INSTRUMENTATION - None

A-10

Name of Dam: HEADVILLE DAM
NDI # PA 00177

VISUAL EXAMINATION OBSERVATIONS REMARKS OR RECOMMENDATIONS

MONUMENTATION/SURVEYS

OBSERVATION WELLS

WEIRS

PIEZOMETERS

OTHER

RESERVOIR

A-11

Name of Dam: MEADVILLE DAM
NDI # PA 00177

| VISUAL EXAMINATION OF | OBSERVATIONS | REMARKS OR RECOMMENDATIONS |
|------------------------------|---------------------|-----------------------------------|
|------------------------------|---------------------|-----------------------------------|

SLOPES

The slopes are gentle to moderately steep with well established tree and grass cover.

SEDIMENTATION


No sedimentation studies have been performed, but sedimentation of the reservoir is believed to be minimal.

DOWNSTREAM CHANNEL

Name of Dam: MEADVILLE DAM
 NDI # PA 001177

| VISUAL EXAMINATION OF | OBSERVATIONS | REMARKS OR RECOMMENDATIONS |
|---|---|----------------------------|
| CONDITION (OBSTRUCTIONS, DEBRIS, ETC.) | The downstream area has no signs of previous erosion. The banks were covered with well established vegetation. | |
| SLOPES | The slopes are nearly flat to moderate with a good cover of grasses or stands of trees. | |
| APPROXIMATE NO. OF HOMES AND POPULATION | The city of Meadville has an estimated population of 16,500 persons (1970 census). | |
| | | |
| | | |

(Not to Scale)




FIELD SKETCH

Meadville Dam
NDI No. PA 00177
Penn DER No 20-48
Meadville, PA

North St.

(Not to Scale)



FIELD SKETCH
Meadville Dam
NDI. No. PA 00177
Penn DER No. 20-48
Meadville, PA

APPENDIX B

CHECK LIST - ENGINEERING DATA

CHECK LIST
ENGINEERING DATA
DESIGN, CONSTRUCTION, OPERATION

Name of Dam: MEADVILLE DAM
NDI # PA 00177

| <u>ITEM</u> | <u>REMARKS</u> |
|----------------------------|---|
| PLAN OF DAM | See Plates 3, 4, and 5. |
| REGIONAL VICINITY MAP | See Plate 1, a USGS 7.5 minute quadrangle map showing dam location with state location inset. |
| CONSTRUCTION HISTORY | Information from the PennDER files indicate the dam was constructed in 1963 and 1964 by the Smith Construction Company, Ohio. |
| TYPICAL SECTIONS OF DAM | See Plates 6, 9, and 10. |
| HYDROLOGIC/HYDRAULIC DATA | Design computations are included in the SCS "Design Report". |
| OUTLETS - PLAN | See Plate 4. |
| - DETAILS | See Plates 6 and 8. |
| - CONSTRAINTS | See Plate 7. |
| - DISCHARGE RATINGS | None available |
| RAINFALL/RESERVOIR RECORDS | None available |

Name of Dam: HEADVILLE DAM
NDI # PA 00177

B-2

| ITEM | REMARKS |
|------|---------|
|------|---------|

| | |
|----------------|---|
| DESIGN REPORTS | The SCS report, "Mill Run Watershed, Site PA 460, Vol. 2." was available through PennDER. |
|----------------|---|

GEOLOGY REPORTS See Appendix E.

| | |
|------------------------|--|
| DESIGN COMPUTATIONS | Design computations were done by the SCS for hydrology and hydraulics. Seepage and |
| HYDROLOGY & HYDRAULICS | stability studies were also done by the SCS. |
| DAM STABILITY | |
| SEEPAGE STUDIES | |

| | |
|--------------------------|---|
| MATERIALS INVESTIGATIONS | A foundation and borrow investigation was performed with test pits and test borings |
| BORING RECORDS | (see Plates 3 and 4); the computations are contained in the SCS "Design Report." |
| LABORATORY | |
| FIELD | |

| | |
|----------------------------------|---|
| POST-CONSTRUCTION SURVEYS OF DAM | The dam is inspected yearly by the SCS and personnel from the city of Headville, Department of Public Works. |
|----------------------------------|---|

| | |
|----------------|--|
| BORROW SOURCES | Boring and Test Pit Logs. Reference Drawings - Plates 3 and 4. |
|----------------|--|

Name of Dam: MEADVILLE DAM
NOI # PA 00177

B-3

ITEM

REMARKS

MONITORING SYSTEMS No monitoring systems were designed into the dam.

MODIFICATIONS None

HIGH POOL RECORDS None available

POST-CONSTRUCTION ENGINEERING During May 1964, the SCS investigated the structure by boring several holes in
STUDIES AND REPORTS the embankment to obtain samples for shear tests, moisture density relation-
ships, and other as determined necessary at the time of investigation. The
results are contained in the PenNDEr files.

PRIOR ACCIDENTS OR FAILURE OF DAM None
DESCRIPTION
REPORTS

MAINTENANCE Yearly inspections are made by the SCS along with personnel from the city of Meadville, Department of
OPERATION Public Works. Maintenance performed has included erosion repair, liming, fertilizing, seeding, and
RECORDS mowing of the embankment and surrounding areas.

Name of Dam: MEADVILLE DAM
NDI # PA 00177

B-4

| ITEM | REMARKS |
|------|---------|
|------|---------|

SPIILLWAY PLAN See Plate 4.

SECTIONS See Plates 9 and 10.

DETAILS See Plate 8.

**OPERATING EQUIPMENT
PLANS & DETAILS**

A water control gate is provided in the riser; however, at the time of inspection it was not operating correctly. Plans and details are shown on Plate 6. During periods of heavy rains the water level is monitored by city of Meadville, Department of Public Works personnel.

**CHECK LIST
HYDROLOGIC AND HYDRAULIC DATA
ENGINEERING DATA**

B-5

DRAINAGE AREA CHARACTERISTICS: 7.96 sq.mi. (primarily forested)

ELEVATION TOP NORMAL POOL (STORAGE CAPACITY): 1163.5 ft. (30 ac.-ft.)

ELEVATION TOP FLOOD CONTROL POOL (STORAGE CAPACITY): 1189.5 ft.
(850 ac.-ft.)

ELEVATION MAXIMUM DESIGN POOL: 1189.8 ft.

ELEVATION TOP DAM: 1189.8 ft. (Design), 1189.5 ft. (Minimum)

CREST: Auxiliary (Emergency) Spillway

- a. Elevation 1183.3 ft.
- b. Type Reinforced concrete weir box and chute channel
- c. Width 50 ft.
- d. Length Approximately 316 ft.
- e. Location Spillover Adjacent to right abutment
- f. Number and Type of Gates None

OUTLET WORKS: Principal Spillway

- a. Type Drop-inlet with 42-in. R.C.P.
- b. Location Approximately 230 ft. from left abutment
- c. Entrance inverts El. 1150.0 ft.
- d. Exit inverts El. 1147.0 ft.
- e. Emergency draindown facilities 18 in. B.C.C.M.P. pond drain

HYDROMETEOROLOGICAL GAGES: None

- a. Type _____
- b. Location _____
- c. Records _____

MAXIMUM NON-DAMAGING DISCHARGE Unknown

APPENDIX C

PHOTOGRAPHS

DETAILED PHOTOGRAPH DESCRIPTIONS

Overall Views of Dam -

**Top Photo - View of Downstream Embankment
and Concrete Spillway
(Note Erosion Channel on Embankment)**

**Bottom Photo - View of Upstream Face of Dam
from Dike on East Abutment
(Note Ruts and Erosion on Face of Dam)**

**Photo 1 - View from Top of Dam Looking East
Toward Auxiliary Spillway and Dike**

**Photo 2 - View from Dike Looking West
(Normal Pool of Reservoir Left-Center
of Photo behind Baseball Backstop)**

**Photo 3 - View of Grass-Lined Auxiliary Spillway
Channel from Crest of Ogee Spillway
(Note Energy Dissipaters at Bottom of Ogee Spillway)**

Photo 4 - View Looking Downstream from Outlet Pipe

Photo 5 - View of Riser Located at Toe of Upstream Embankment


**Photo 6 - View of Head Wall and Outlet Structure
at Toe of Downstream Embankment
(Note Erosion between Structure and Fence)**

Photo 7 - View from South End of Auxiliary Spillway


Photo 8 - Close-up View of South End of Auxiliary Spillway

Note: Photographs were taken on 1 December 1978.

MEADVILLE DAM



**PHOTO 1. View from Top of Dam Looking East Toward
Auxiliary Spillway and Dike**



**PHOTO 2. View from Dike Looking West (Normal Pool of Reservoir
Left-Center of Photo behind Baseball Backstop)**

MEADVILLE DAM




PHOTO 3. View of Grass-Lined Auxillary Spillway Channel from Crest of Ogee Spillway (Note Energy Dissipaters at Bottom of Ogee Spillway)



PHOTO 4. View Looking Downstream from Outlet Pipe

MEADVILLE DAM




PHOTO 5. View of Riser Located at Toe of Upstream Embankment



PHOTO 6. View of Head Wall and Outlet Structure at Toe of Downstream Embankment (Note Erosion between Structure and Fence)

MEADVILLE DAM




PHOTO 7. View from South End of Auxilliary Spillway




PHOTO 8. Close-up View of South End of Auxilliary Spillway

APPENDIX D

HYDROLOGIC AND HYDRAULIC COMPUTATIONS

MICHAEL BAKER, JR., INC.

THE BAKER ENGINEERS

Box 280
Beaver, Pa. 15009

Subject Meadville Dam

S.O. No. _____

Sheet No. _____ of _____

Drawing No. _____

Computed by _____ Checked by _____ Date _____

Table of Contents

| | |
|--------------------------------------|----|
| Preface | i |
| Rainfall and hydrograph data | 1 |
| Watershed Plan & Downstream Area Map | 2 |
| Principal Spillway Rating | 3 |
| Stage vs. Discharge | 4 |
| Stage vs. storage | 6 |
| Profile Top of Dam and Dyke | 7 |
| Flood Routing through Tamarack Lake | 8 |
| Channel Routing Data | 13 |
| Flood Routing through Meadville Dam | 14 |

PREFACE

HYDROLOGIC AND HYDRAULIC COMPUTATIONS

The hydrologic determinations presented in this Phase I Inspection Report are based on the use of a Snyder's unit hydrograph developed by the U.S. Army Corps of Engineers. Due to the limited number of gaging stations available in this hydrologic region and the wide variation of watershed slopes, the Snyder's coefficients may yield results of limited accuracy for this watershed. As directed however, a further refinement of these coefficients is beyond the scope of this Phase I Investigation.

In addition, the conclusions presented pertain to present conditions, and the effect of future development on the hydrology has not been considered.

MICHAEL BAKER, JR., INC.
THE BAKER ENGINEERS

Box 280
Beaver, Pa. 15009

Subject Meadville Dam S.O. No. _____
Rainfall and Hydrograph Data Sheet No. 1 of 20
Uncontrolled Drainage Area Drawing No. _____
Computed by G.G.S. Checked by REH Date 3-2-79

Rainfall from HMR-33

PMP $24 \text{ hr} \cdot 200 \text{ mi}^2 = 23.4 \text{ in}$

D.D. = 2.97 sq mi
located in Zone 2
(Uncontrolled
Drainage Area)

$P_{6 \text{ hr}} = 117\% \text{ PMP}$

$P_{12 \text{ hr}} = 121\% \text{ PMP}$

$P_{18 \text{ hr}} = 141\% \text{ PMP}$

$P_{24 \text{ hr}} = 151\% \text{ PMP}$

Hydrograph located in Zone 23 (Ohio River Basin)

$$t_p = 3.3(L + L_{ca})^{0.3}$$

$$L = 3.03 \text{ mi}$$

$$L_{ca} = 1.91 \text{ mi}$$

$$C_p = 0.55$$

$$t_r = 20 \text{ min}$$

$$t_p = 3.3(L + L_{ca})^{0.3}$$

$$= 3.3(3.03 + 1.91)^{0.3}$$

$$= 5.59 \text{ hrs}$$


$$t_r = t_p / 5.5$$

$$= 1.02 \text{ hrs}$$

$$t_{pe} = t_p + 0.25(t_p - t_r)$$

$$= 5.59 + 0.25(5.59 - 1.02)$$

$$= 5.42 \text{ hrs}$$



Quads: 1. Meadville
2. Blooming Valley
3. Cochranston
4. Geneva

Drainage Area = 2.97 mi.²
L = 3.03 mi. Lca = 1.91 mi.

0 2000 4000
SCALE IN FEET

DATE: 3-29-79

Mill Run Watershed
at
Meadville Dam

MICHAEL BAKER JR. INC.
Consulting Engineers & Surveyors

MICHAEL BAKER, JR., INC.
THE BAKER ENGINEERS

Box 280
Beaver, Pa. 15009

Subject Meadville Dam
Downstream Area Map

Computed by REH


Checked by

S.O. No. _____

Sheet No. 26 of 20

Drawing No. _____

Date 4-25-79



2000 0 2000 4000
Scale in feet

MICHAEL BAKER, JR., INC.
THE BAKER ENGINEERS

Box 280
Beaver, Pa. 15009

Subject Meadville Dam

Principal Spillway Rating

S.O. No. _____

Sheet No. 3 of 20

Drawing No. _____

Computed by G.A.S.

Checked by REH

Date _____

Nick flow: (Q_N)

$$Q_N = C_d H^{3/2}$$

$$Q_N = 3.1(10) H^{3/2}$$

$$Q_N = 49.6 H^{3/2}$$

Pipe flow: (Q_P)

From figure B-10

Design of Small Dams

$$L = 177 \text{ ft.}$$

$$K_e = 0.5$$

$$D = 42 \text{ in.}$$

| Elev. (ft.) | H _m (ft.) | Q _N (cfs) | h _p (ft.) | Q _P (cfs) |
|----------------|-------------------------|-------------------------|-------------------------|-------------------------|
| 1164 | 0.5 | 18 | 14 | 185 |
| 1165 | 1.5 | 91 | 15 | 190 |
| 1166 | 2.5 | 196 | 16 | 196 |
| 1167 | 3.5 | 325 | 17 | 202 |
| 1168 | 4.5 | 475 | 18 | 208 |
| 1169 | | | 19 | 214 |
| 1170 | | | 20 | 220 |
| 1171 | | | 21 | 226 |
| 1172 | | | 22 | 232 |
| 1173 | | | 23 | 238 |
| 1174 | | | 24 | 244 |
| 1175 | | | 25 | 250 |
| 1176 | | | 26 | 255 |
| 1177 | | | 27 | 260 |
| 1178 | | | 28 | 265 |
| 1179 | | | 29 | 270 |
| 1180 | | | 30 | 275 |
| 1181 | | | 31 | 278 |
| 1182 | | | 32 | 281 |
| 1183 | | | 33 | 283 |
| 1184 | | | 34 | 285 |
| 1189 | | | 39 | 310 |

MICHAEL BAKER, JR., INC.
THE BAKER ENGINEERS

Box 280
Beaver, Pa. 15009

Subject Meadville Dam
Stage vs. Discharge

S.O. No. _____

Sheet No. 4 of 20

Drawing No. _____

Computed by P.A.S. Checked by REH Date 3-7-79

| Stage (feet) | Q _{meas} (cfs) | Q _{pipe} (cfs) | Q _{ams} [*] (cfs) | Q _{total} (cfs) |
|-----------------|----------------------------|----------------------------|--|-----------------------------|
| 116.4 | 78 | 186 | | 18 |
| 116.5 | 91 | 190 | | 91 |
| 116.6 | 196 | 196 | | 196 |
| 116.7 | 325 | 202 | | 202 |
| 116.8 | 473 | 208 | | 208 |
| 116.9 | | 214 | | 214 |
| 117.0 | | 220 | | 220 |
| 117.1 | | 226 | | 226 |
| 117.2 | | 232 | | 232 |
| 117.3 | | 238 | | 238 |
| 117.4 | | 246 | | 244 |
| 117.5 | | 250 | | 250 |
| 117.6 | | 255 | | 255 |
| 117.7 | | 260 | | 260 |
| 117.8 | | 265 | | 265 |
| 117.9 | | 270 | | 270 |
| 118.0 | | 275 | | 275 |
| 118.1 | | 278 | | 278 |
| 118.2 | | 281 | | 281 |
| 118.3 | | 285 | | 285 |
| 118.4 | | 288 | | 288 |
| 1184.3 | | 286 | | 286 |
| 1184.5 | | 288 | 12 | 360 |
| 1184.5 | | 289 | 286 | 575 |
| 1185.3 | | 292 | 870 | 1102 |
| 1185.8 | | 294 | 1491 | 1785 |

MICHAEL BAKER, JR., INC.
THE BAKER ENGINEERS

Box 280
Beaver, Pa. 15009

Subject Meadville Dam

Stage vs. Discharge

S.O. No. _____

Sheet No. 5 of 20

Drawing No. _____

Computed by G. G. S. Checked by REN

Date 3-7-79

| Stage | Q_{WEIR} | Q_{PIPS} | Q_{EMS}^* | Q_{TOTAL} |
|--------|------------|------------|-------------|-------------|
| 1186.3 | | 297 | 2301 | 2598 |
| 1186.8 | | 299 | 3223 | 3522 |
| 1187.3 | | 302 | 4246 | 4548 |
| 1187.8 | | 304 | 5363 | 5667 |
| 1188.3 | | 307 | 6567 | 6874 |
| 1188.8 | | 309 | 7854 | 8163 |
| 1189.3 | | 312 | 9219 | 9531 |
| 1189.8 | | 314 | 10661 | 10975 |
| 1190.3 | | 317 | 12176 | 12493 |


* Q_{EMS} Emergency Spillway was taken from the
SC Design Report for Meadville Dam.

MICHAEL BAKER, JR., INC.
THE BAKER ENGINEERS

Box 280
Beaver, Pa. 15009

Subject Meadville Dam S.O. No. _____
Stage vs. Storage Sheet No. 6 of 20
(from SCS Design Report) Drawing No. _____
Computed by G.A.S. Checked by R.H. Date 3-6-79

| Stage (ft.) | Storage (A-F) |
|----------------|------------------|
| 1151.0 | 0 |
| 1151.2 | 5.82 |
| 1162.0 | 26.12 |
| 1163.0 | 67.82 |
| 1172.0 | 91.82 |
| 1173.0 | 181.42 |
| 1182.0 | 361.32 |
| 1183.0 | 656.62 |
| 1192.0 | 1108.12 |



MICHAEL BAKER, JR., INC.
THE BAKER ENGINEERS

Box 280
Beaver, Pa. 15009

Subject Meadville Dam
Top of Dam Profile


Computed by G.G.S. Checked by _____

S.O. No. _____

Sheet No. 7 of 20

Drawing No. _____

Date 3-7-79



 FLOOD HYDROGRAPH PACKAGE (HEC-1)
 DAM SAFETY VERSION JULY 1978
 LAST MODIFICATION 25 SEP 78

NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS
 HYDROLOGIC AND HYDRAULIC ANALYSIS OF TAMARACK LAKE A & B
 PROBABLE MAXIMUM FLOOD PMF/UNIT GRAPH BY SHYDERS METHOD

| | | | | | | | | | | | |
|----|----|------|-------|------|------|------|---------|---------|---------|---------|---------|
| 1 | A1 | 300 | 0 | 20 | 0 | 0 | 0 | 0 | 0 | -4 | 0 |
| 2 | A2 | 5 | 1 | 1 | | | | | | | |
| 3 | A3 | 1.0 | 1 | | | | | | | | |
| 4 | B1 | 0 | 1 | | | | | | | | |
| 5 | B2 | 1 | | | | | | | | | |
| 6 | J1 | 1.0 | | | | | | | | | |
| 7 | K | 0 | | | | | | | | | |
| 8 | K1 | 1 | | | | | | | | | |
| 9 | M | 1 | 4.99 | 4.99 | | | | | | | |
| 10 | P | 1 | 23.4 | 117 | 127 | 141 | 151 | | | | |
| 11 | T | | | | | | | 1.0 | 0.02 | | |
| 12 | W | 3.06 | 0.55 | | | | | | | | |
| 13 | X | -1.5 | -0.05 | 2.0 | | | | | | | |
| 14 | K | 1 | | | | | | | | | |
| 15 | K1 | 1 | | | | | | | | | |
| 16 | Y | | | | | | | | | | |
| 17 | Y1 | | | | | | | | | | |
| 18 | V1 | | | | | | | | | | |
| 19 | V4 | 1216 | 1217 | 1218 | 1219 | 1220 | 1220.90 | 1221.71 | 1222.57 | 1223.30 | 1223.91 |
| 20 | V5 | 0 | 14 | 35 | 105 | 139 | 767 | 1933 | 3758 | 5592 | 7462 |
| 21 | S5 | 3850 | 4400 | 5000 | 5600 | 6200 | 6800 | 7330 | 8150 | 8700 | 9050 |
| 22 | S6 | 1216 | 1217 | 1218 | 1219 | 1220 | 1221 | 1222 | 1223 | 1224 | 1225 |
| 23 | S8 | 1216 | | | | | | | | | |
| 24 | S0 | 1223 | 2.65 | 1.5 | 1800 | | | | | | |
| 25 | K | 99 | | | | | | | | | |

THIS IS A ROUTING FOR TAMARACK LAKE

Note: for additional information see the report for Tamarack Lake Dam A

Sheet 8 of 20

FLOOD HYDROGRAPH PACKAGE (HFC-1)
DAM SAFETY VERSION JULY 1978
LAST MODIFICATION 25 SEP 78

RUN DATE 04/24/79
TIME 16.18

NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS
HYDROLOGIC AND HYDRAULIC ANALYSIS OF TAMARACK LAKE A 6 0
PROBABLE MAXIMUM FLOOD PRE/UNIT GRAPH BY SNYDER'S METHOD

| NQ | MHR | MMIN | IDAY | IMR | IMIN | METC | IPLT | IPRT | MSTAN |
|-----|-----|------|-------|-----|-------|-------|------|------|-------|
| 300 | 0 | 20 | 0 | 0 | 0 | 0 | 0 | -4 | 0 |
| | | | JOPER | NWT | LROPT | TRACE | | | |
| | | | 5 | 0 | 0 | 0 | | | |

JOB SPECIFICATION

MULTI-PLAN ANALYSES TO BE PERFORMED

NPLAN= 1 NRTIO= 1 LRTIO= 1

RTIOS= 1.00

SUB-AREA RUNOFF COMPUTATION

HYDROGRAPH FOR OVERLAND FLOW

| ISTAQ | ICOMP | IECON | ITAPE | JPLI | JPRI | IMANE | ISTAGE | IAUTO |
|-------|-------|-------|-------|------|------|-------|--------|-------|
| 1 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 |

HYDROGRAPH DATA

| IHYDG | IUNG | TAREA | SNAP | TRSDA | TRSPC | RATIO | ISNOW | ISAME | LOCAL |
|-------|------|-------|------|-------|-------|-------|-------|-------|-------|
| 1 | 1 | 4.99 | 0.0 | 4.99 | 0.0 | 0.0 | 0 | 0 | 0 |

PRECIP DATA

| SPFE | PMS | R6 | R12 | R24 | R48 | R72 | R96 |
|------|-------|--------|--------|--------|--------|-----|-----|
| 0.0 | 23.60 | 117.00 | 127.00 | 141.00 | 151.00 | 0.0 | 0.0 |

TRSPC COMPUTED BY THE PROGRAM IS 0.800

LOSS DATA

| LROPT | STRKR | DLTKR | RTIOL | ERAIN | STRSK | RTIOK | STATL | CNSTL | ALSMX | RTIMP |
|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|
| 0 | 0.0 | 0.0 | 1.00 | 0.0 | 0.0 | 1.00 | 1.00 | 0.05 | 0.0 | 0.0 |

UNIT HYDROGRAPH DATA

TP= 3.06 CP=0.55 NTA= 0

RECESSION DATA

STRTO= -1.50 ORCSN= -0.05 RTIOR= 2.00

UNIT HYDROGRAPH 62 END-OF-PERIOD ORIGINATES, LAG= 3.08 HOURS, CP= 0.55 VOL= 1.00

| | | | | | | | | |
|------|------|------|------|------|------|------|------|------|
| 19. | 72. | 145. | 231. | 325. | 418. | 496. | 551. | 588. |
| 556. | 506. | 461. | 420. | 382. | 349. | 317. | 289. | 260. |
| 218. | 199. | 181. | 165. | 150. | 137. | 124. | 113. | 94. |
| 86. | 78. | 71. | 65. | 59. | 54. | 49. | 44. | 37. |
| 34. | 31. | 28. | 25. | 23. | 21. | 19. | 17. | 16. |

Sheet 9 of 20

| 0 | | END-OF-PERIOD FLOW | | | | | | | | | | | |
|-------|-------|--------------------|------|------|------|--------|-------|-------|--------|------|------|------|--------|
| MO.DA | HR.MN | PERIOD | RAIN | EXCS | LOSS | COMP Q | MO.DA | HR.MN | PERIOD | RAIN | EXCS | LOSS | COMP Q |
| 13. | 5. | | 12. | 5. | | | 9. | 0. | 8. | 7. | 6. | 6. | |
| | | | 11. | | | | 10. | | | | | | |

END-OF-PERIOD FLOW

| | | | | |
|-----|----------|----------|---------|------------|
| SUM | 20.27 | 25.03 | 2.44 | 251211. |
| | (718.1) | (656.1) | (62.1) | (7113.51) |

HYDROGRAPH ROUTING

THIS IS A ROUTING FOR TAMARACK LAKE

| ISTAQ | ICOMP | TECON | ITYPE | JPLT | JPRY | INAME | ISTAGE | IAUTO |
|-------|-------|-------|-------|------|------|-------|--------|-------|
| DAM | 1 | 0 | 0 | 0 | 0 | 1 | 0 | 0 |

| ROUTING DATA | | | | | | |
|--------------|-----|-----|-------|------|------|------|
| CROSS | AVG | RES | ISAME | IOPT | IPNP | LSTR |
| 0-0 | 0-0 | 1 | 1 | 0 | 0 | 0 |

| NSIPS | NSIOL | LAG | AMSK | X | TSK | STORA | ISPRAT |
|-------|-------|-----|------|---|-----|-------|--------|
| 0.0 | 0.0 | 1 | 1 | 0 | 0 | 0 | 0 |

| | | | | | | | |
|---|---|---|---|---|---|--------|-----|
| 0 | 0 | 0 | 0 | 0 | 0 | -1216. | -10 |
|---|---|---|---|---|---|--------|-----|

| | | | | |
|---------|---------|---------|---------|---------|
| 1216.00 | 1219.00 | 1220.00 | 1220.90 | 1221.71 |
|---------|---------|---------|---------|---------|

| | | | | |
|-------|--------|--------|--------|---------|
| 35.00 | 105.00 | 132.00 | 767.00 | 1933.00 |
|-------|--------|--------|--------|---------|

5000. 5600. 6200. 6880. 7530. 8150.

| | | | | | |
|-------|-------|-------|-------|-------|-------|
| 1218. | 1219. | 1220. | 1221. | 1222. | 1223. |
|-------|-------|-------|-------|-------|-------|

| L | SPWID | CQOM | EXPW | ELEVL | COOL | CAREA | EXPL |
|---|-------|------|------|-------|------|-------|------|
| 0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 |

DAM DATA

| TOPEL | COOD | EXPD | DAMWID |
|--------|------|------|--------|
| 1223-0 | 2.6 | 1.5 | 1900. |

46.67 HOURS

.....

.....

Sheet 10 of 20

17

HYDRO/FORM 1011-1-68

PRINTED IN U.S.A.

| PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS | | | |
|---|---------|--------|--------------|
| FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND) | | | |
| AREA IN SQUARE MILES (SQUARE KILOMETERS) | | | |
| OPERATION | STATION | AREA | PLAN RATIO 1 |
| RATIOS APPLIED TO FLOWS | | | |
| HYDROGRAPH AT | 1 | 4.99 | 1 |
| | (| 12.92) | (|
| | | | 9978. |
| | | | (|
| | | | 282.55) |
| ROUTED TO | DAM | 4.99 | 1 |
| | (| 12.92) | (|
| | | | 4609. |
| | | | (|
| | | | 130.52) |

Sheet 11 of 20

三

Sheet 12 of 20

MICHAEL BAKER, JR., INC.
THE BAKER ENGINEERS

Box 280
Beaver, Pa. 15009

Subject Meadville Dam

Channel Routing Data

S.O. No. _____

Sheet No. 13 of 20


Drawing No. _____

Computed by G.A.S.

Checked by REH

Date 3-7-79

*Typical Cross-section used
in Channel Routing Analysis*



The outflow from Tamarack Dam A was routed
2500 feet downstream to the flood pool
created by Meadville Dam. Parameters used
in the routing are:

slope of channel = 0.003

channel roughness (n) = 0.04

overbank roughness = 0.08

ELOOD HYDROGRAPH PACKAGE (HEC-1)
DAM SAFETY VERSION JULY 1978
LAST MODIFICATION 25 SEP 78

NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS
HYDROLOGIC AND HYDRAULIC ANALYSIS OF MEADVILLE DAM MBJ 01
PROBABLE MAXIMUM FLOOD PMF/UNIT GRAPH BY SNYDERS METHOD

DISCHARGE FROM TAMPAK LAKE DAM A (See note on following page)

Sheet 14 of 20

3 CHANNEL ROUTING LAKE TAMARACK TO HEADVILLE DAM MOD PULS

6
SNYDER HYDROGRAPH FOR UNCONTROLLED RUNOFF TO HEADEVILLE DAM

 FLOOD HYDROGRAPH PACKAGE (HEC-1)
 DAM SAFETY VERSION JULY 1978
 LAST MODIFICATION 25 SEP 78

RUN DATE 06/24/79
 TIME 14.11

NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS
 HYDROLOGIC AND HYDRAULIC ANALYSIS OF HEADVILLE DAM NOJ 01
 PROBABLE MAXIMUM FLOOD PMF/UNIT GRAPH BY SNYDER'S METHOD

| JOB SPECIFICATION | | | | | | | | | |
|-------------------|-----|------|-------|-----|-------|-------|------|------|--------|
| NQ | MHR | MMIN | IDAY | IMR | IMIN | METRC | IPLT | IPRT | INSTAN |
| 300 | 0 | 20 | 0 | 0 | 0 | 0 | 0 | -4 | 0 |
| | | | JOPER | MUT | LROPT | TRACE | | | |
| | | | 5 | 0 | 0 | 0 | | | |

MULTI-PLAN ANALYSES TO BE PERFORMED
 MPLAN= 1 MPTIO= 1 LATIO= 1

RTIOS= 1.00

SUB-AREA RUNOFF COMPUTATION

DISCHARGE FROM TAMARACK LAKE DAM A

| ISTAQ | ICOMP | IECON | ITAPE | JPLT | JPRT | INAME | ISTAGE | IAUTO |
|-------|-------|-------|-------|------|------|-------|--------|-------|
| 4 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 |

HYDROGRAPH DATA

| IMYOG | IUNG | TAREA | SNAP | TRSDA | TRSPC | RATIO | ISHOW | ISAME | LOCAL |
|-------|------|-------|------|-------|-------|-------|-------|-------|-------|
| -1 | 0 | 4.99 | 0.0 | 4.99 | 0.0 | 0.0 | 0 | 0 | 0 |

CHANNEL ROUTING LAKE TAMARACK TO HEADVILLE DAM MOD PULS

| ROUTING DATA | | | | | | | | | |
|--------------|-------|-------|-------|-------|------|-------|--------|-------|--|
| ISTAQ | ICOMP | IECON | ITAPE | JPLT | JPRT | INAME | ISTAGE | IAUTO | |
| 5 | 1 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | |
| ROUTING DATA | | | | | | | | | |
| QLOSS | CLOSS | AVG | IPRES | ISAME | IQPT | IPMP | LSTR | | |
| 0.0 | 0.0 | 0.0 | 1 | 1 | 0 | 0 | 0 | | |
| ROUTING DATA | | | | | | | | | |
| NSTPS | NSTD | LAG | ANSKK | X | TSK | STORA | ISPRAT | | |
| 1 | 0 | 0 | 0.0 | 0.0 | 0.0 | 0 | 0 | | |

NORMAL DEPTH CHANNEL ROUTING

Sheet 16 of 20

QNI(1) QNI(2) QNI(3) FLNVT ELMAX RLNTH SEL
0.0800 0.0400 0.0800 1181.6 1189.0 5500. 0.00300

CROSS SECTION COORDINATES--STA.ELEV,STA.ELEV--ETC

0.0 1201.60 900.00 1191.60 1640.00 1184.60 1640.00 1181.60 1640.00 1181.60

1660.00 1183.60 2000.00 1191.60 2150.00 1201.00

STORAGE 0.0 0.98 1.97 2.95 3.93 4.92 6.20 8.30 11.29 16.62

24.79 35.80 49.64 66.33 85.85 108.20 133.40 161.43 192.30 226.01

OUTFLOW 0.0 8.26 25.59 49.12 77.55 110.03 148.03 194.23 252.03 330.42

439.11 586.81 781.10 1028.87 1336.56 1710.23 2155.66 2678.38 3283.74 3976.89

STAGE 1181.60 1181.99 1182.38 1182.77 1183.16 1183.55 1183.94 1184.33 1184.72 1185.10

1185.49 1185.88 1186.27 1186.66 1187.05 1187.44 1187.83 1188.22 1188.61 1189.00

FLOW 0.0 8.26 25.59 49.12 77.55 110.03 148.03 194.23 252.03 330.42

439.11 586.81 781.10 1028.87 1336.56 1710.23 2155.66 2678.38 3283.74 3976.89

MAXIMUM STAGE IS 1188.1

SUB-AREA RUNOFF COMPUTATION

SNYDER HYDROGRAPH FOR UNCONTROLLED RUNOFF TO MEADEVILLE DAM

ISTAQ ICOMP IECON ITAPE JPLT JPRAT INAME ISTAGE IAUTO

HYDROGRAPH DATA
IHYDC IUNG TAREA SHAP TRSDA TRSPC RATIO ISNOW ISAME LOCAL

PRECIP DATA
SPFE PMS R6 R12 R24 R48 R72 R96

TRSPC COMPUTED BY THE PROGRAM IS 0.800

LOSS DATA

LAOPT STRKR DLTRK RTIOL ERAIN STRKS RTIOK STATL CMSTL ALSHX RTIMP

UNIT HYDROGRAPH DATA
TP= 5.42 CP=0.55 NTA= 0

RECESSION DATA

STRTO= -1.20 ORCSN= -0.05 RTIOR= 2.00

UNIT HYDROGRAPH END-OF-PERIOD ORIGINATES, LAG= 5.44 HOURS, CP= 0.55 VOL= 0.79

3. 11. 23. 36. 52. 69. 87. 105. 124. 143.
159. 172. 183. 192. 198. 200. 199. 193. 183. 174.
165. 157. 149. 141. 134. 127. 121. 114. 109. 103.
98. 88. 79. 72. 64. 57. 50. 42. 36. 30.
58. 55. 52. 47. 45. 42. 40. 38. 36. 34.
34. 33. 29. 28. 26. 25. 24. 23. 21. 20.
20. 19. 18. 17. 16. 15. 14. 13. 12. 11.
7. 6. 5. 4. 3. 2. 1. 0. 0. 0.
4. 4. 4. 4. 4. 4. 4. 4. 4. 4.

MO.DA HR.MN PERIOD RAIN EXCS LOSS END-OF-PERIOD FLOW MD.DA HR.MN PERIOD RAIN EXCS LOSS COMP Q

SUM 20.27 25.83 2.44 147813.
(710.11 656.11 62.11 4185.60)

COMBINE HYDROGRAPHS

HYDROGRAPH FOR DISCHARGE LAKE TAMARACK AND UNCONTROLLED RUNOFF

| ISTAQ | ICOMP | TECON | ITAPE | JPLT | JPRY | INAME | ISTAGE | IAUTO |
|-------|-------|-------|-------|------|------|-------|--------|-------|
| 7 | 2 | 0 | 0 | 0 | 0 | 1 | 0 | 0 |

HYDROGRAPH ROUTING

THIS IS A ROUTING FOR HEADEVILLE DAM

| TSTAQ | ICOMP | TECON | ITAPE | JPLT | JPRY | INAME | ISTAGE | IAUTO |
|-------|-------|-------|-------|------|------|-------|--------|-------|
| DAM | 1 | 0 | 0 | 0 | 0 | 1 | 0 | 0 |

ROUTING DATA

| GLOSS | CLOSS | AVG | IRCS | ISAME | IOPT | IPMP | LSTR |
|-------|-------|-----|------|-------|------|------|------|
| 0.0 | 0.0 | 0.0 | 1 | 1 | 0 | 0 | 0 |

| NSTPS | MSDOL | LAG | ANSKK | X | YSK | STORA | ISPRAT |
|-------|-------|-----|-------|-----|-----|--------|--------|
| 0 | 0 | 0 | 0.0 | 0.0 | 0.0 | -1164. | -1 |

| STAGE | 1163.50 | 1165.00 | 1167.00 | 1169.00 | 1171.00 | 1173.00 | 1175.00 | 1177.00 | 1179.00 | 1181.00 |
|-------|---------|---------|---------|---------|---------|---------|---------|---------|---------|---------|
| | 1163.00 | 1164.30 | 1165.30 | 1166.30 | 1167.30 | 1168.30 | 1169.30 | 1170.30 | 1171.00 | 1172.00 |

| FLOW | 0.0 | 91.00 | 202.00 | 214.00 | 226.00 | 238.00 | 250.00 | 260.00 | 270.00 | 278.00 |
|------|--------|--------|---------|---------|---------|---------|---------|----------|--------|--------|
| | 283.00 | 286.00 | 1102.00 | 2598.00 | 4548.00 | 6874.00 | 9531.00 | 12493.00 | 260.00 | 270.00 |

| CAPACITY= | 0. | 6. | 21. | 46. | 92. | 181. | 362. | 657. | 1108. |
|-----------|-------|-------|-------|-------|-------|-------|-------|-------|-------|
| | 1151. | 1157. | 1162. | 1167. | 1172. | 1177. | 1182. | 1187. | 1192. |

| ELEVATION= | 1151. | 1157. | 1162. | 1167. | 1172. | 1177. | 1182. | 1187. | 1192. |
|------------|--------|--------|-------|-------|-------|-------|-------|-------|-------|
| | 1163.5 | 1163.5 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 |

| CREL | SPMID | COOH | EXPM | ELEV | COOL | CAREA | EXPL |
|--------|-------|------|------|------|------|-------|------|
| 1163.5 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 |

| TOPEL | COOD | EXPD | DAMWID |
|--------|------|------|--------|
| 1190.3 | 2.6 | 1.5 | 1436. |

PEAK OUTFLOW IS 5992. AT TIME 46.67 HOURS

Sheet 13 of 20

PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS
 FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

RATIOS APPLIED TO FLOWS

| OPERATION | STATION | AREA | PLAN | RATIO 1 |
|---------------|---------|----------|------|----------|
| | | | | 1.00 |
| HYDROGRAPH AT | 4 | 4.99 | 1 | 2589. |
| | | (12.92) | (| 73.31)(|
| ROUTED TO | 5 | 4.99 | 1 | 2525. |
| | | (12.92) | (| 71.49)(|
| HYDROGRAPH AT | 6 | 2.97 | 1 | 4001. |
| | | (7.69) | (| 113.31)(|
| 2 COMBINED | 7 | 7.96 | 1 | 5943. |
| | | (20.62) | (| 168.29)(|
| ROUTED TO | DAM | 7.96 | 1 | 5892. |
| | | (20.62) | (| 166.85)(|

PLAN 1 STATION 5

| RATIO | MAXIMUM FLOW,CFS | MAXIMUM STAGE,FT | TIME HOURS |
|-------|---------------------|---------------------|---------------|
| 1.00 | 2525. | 1188.1 | 47.67 |

Sheet 19 of 20

Sheet 20 of 20


APPENDIX E

REGIONAL GEOLOGY

MEADVILLE DAM
NDI No. PA 00177, PennDER No. 20-48, SCS No. PA 460

REGIONAL GEOLOGY

Meadville Dam is located in the glaciated section of the Appalachian Plateaus physiographic province. Geologic references indicate that Mill Run, the site of the dam, and much of the city of Meadville are located on Wisconsin stage glacial outwash deposits. Test borings made to obtain subsurface information for design of the dam penetrated interbedded deposits of sand and gravel, sand, and some silt mixed with varying amounts of clay. Some of these borings were drilled as deep as 31 feet without penetrating bedrock. However, geologic references show that bedrock units beneath the glacial deposits are gently dipping members of the Pocono group, Mississippi system as shown on the following map and legend. These units are predominantly gray, hard massive conglomerates and sandstones with some shale.



LEGEND

PERMIAN



Greene Formation

Cyclic sequences of sandstone, shale, red beds, limestone and coal; base at the top of the Upper Washington Limestone.

PERMIAN AND PENNSYLVANIAN



Washington Formation

Cyclic sequences of sandstone, shale, limestone and coal; some red shale; some mineable coal; base at the top of the Waynesburg Coal.

PENNSYLVANIAN

APPALACHIAN PLATEAU



Monongahela Formation

Cyclic sequences of sandstone, shale, limestone and coal; limestone prominent in northern outcrop areas; shale and sandstone increase southward; commercial coals present; base at the bottom of the Pittsburgh Coal.



Conemaugh Formation

Cyclic sequences of red and gray shales and siltstones with thin limestones and coals; massive Mahoning Sandstone commonly present at base; Ames Limestone present in middle of section; Brush Creek Limestone in lower part of section.



Allegheny Group

Cyclic sequences of sandstone, shale, limestone and coal; numerous commercial coals; limestones thicker westward; Venport Limestone in lower part of section; includes Freeport, Mannington, and Clarion Formations.



Pottsville Group

Predominantly sandstones and conglomerates with thin shales and coals; some coals mineable locally.

ANTHRACITE REGION



Post-Pottsville Formations

Brown or gray sandstones and shales with some conglomerates and numerous mineable coals.



Pottsville Group

Light gray to white, coarse grained sandstones and conglomerates with some mineable coal; includes Sharp Mountain, Schuylkill, and Tumbling Run Formations.

MISSISSIPPIAN



Mauch Chunk Formation

Red shales with brown to greenish gray fluggy sandstones; includes Greenbrier Limestone in Fayette, Westmoreland, and Somerset counties; Loyalkanna Limestone at the base in southwestern Pennsylvania.



Pocono Group

Predominantly gray, hard, massive, cross-bedded conglomerate and sandstone with some shale; includes in the Appalachian Plateau Bargoon, Shesango, Cayahoga, Cassawago, Corry, and Knapp Formations; includes part of "Oswayo" of M. L. Fuller in Potter and Tioga counties.

DEVONIAN UPPER

WESTERN PENNSYLVANIA



Oswayo Formation

Greenish gray to gray shales, siltstones and sandstones becoming increasingly shaly westward; considered equivalent to type Oswayo, Riceville Formation Or in Erie and Crawford Counties; probably not distinguishable north of Corry.



Cattaraugus Formation

Red, gray and brown shale and sandstone with the proportion of red decreasing westward; includes Venango sands of drillers and Salamanca sandstone and conglomerate; some limestone in Crawford and Erie counties.



Conneaut Group

Alternating gray, brown, greenish and purplish shales and siltstones; includes "pink rock" of drillers and "Chemung" and "Girard" Formations of northwestern Pennsylvania.



Canadaway Formation

Alternating brown shales and sandstones; includes "Portage" Formation of northwestern Pennsylvania.

END 9-79